Notification dated 24th April 1927.

It is hereby notified that the undermentioned teak pieces found lying unclaimed in Jigannikatte Tank and in the trench around the Begur Inam village, Shikarpur Taluk, are now in the custody of Patels Buramanna of Bendekatte and Ramappa of Begur. They do not bear numbers or marks of any description. Any person having any right to them is directed to present to the District Forest Officer, Sagar Division, within one month from the date of publication of this notice, a written statement of his claims and establish his rights thereto failing which the ownership of the said pieces will vest in Government under Section 42 of the Mysore Forest Regulation :—

Jiganikatte Tank. Teak pieces round.

		C.ft.
1	15—2 ;	1—8=3
2	12—0 ;	1—8=2
3	11—0 ;	1—7=2
4	11—6 ;	1—6=2
5	13—6 ;	1—6=2
6	14—6 ;	1—7=2
7	7—0 ;	1—2=1
8	8—0 ;	1—7=1
9	2—6 ;	1—8=2
10	10—0 ;	1—4=1
11	12—0 ;	1—4=1
12	10—0 ;	1—7=2
13	12—0 ;	1—3=1
14	13—6 ;	1—4=2
15	8—6 ;	1—8=1
16	12—0 ;	1—4=1
17	15—0 ;	1—5=2
18	14—0 ;	1—3=1
19	14—0 ;	1—3=1
20	14—6 ;	1—4=2
	Total ...	32

Timber found in the trench.

1	22—6 ;	1—9=4
2	22—6 ;	1—9=4
3	19—9 ;	2—0=5
4	15—6 ;	1—8=2
5	9—8 ;	2—2=3
6	10—0 ;	2—10=5
7	15—9 ;	2—0=4
8	16—0 ;	2—2=5
9	11—0 ;	1—5=1
10	8—0 ;	1—2=1
11	21—6 ;	1—5=3
12	10—0 ;	1—0=1
13	10—6 ;	1—5=1
14	8—0 ;	1—8=1
15	20—0 ;	1—6=3
16	8—0 ;	1—4=1
17	8—0 ;	1—8=1
18	9—0 ;	1—2=1
19	8—0 ;	1—5=1
20	17—0 ;	1—6=2
21	13—0 ;	1—7=2
22	15—0 ;	1—6=2
23	9—6 ;	1—6=1
24	20—0 ;	1—8=3
25	19—0 ;	1—5=2
26	8—0 ;	1—0=1
27	1—0 ;	1—2=1
28	11—6 ;	3—0=7
29	10—0 ;	8—0=1
30	17—0 ;	1—6=2
31	14—0 ;	1—8=2
32	10—6 ;	3—0=6
33	6—0 ;	2—10=3
34	0—0 ;	1—7=1
35	15—6 ;	2—2=4
36	19—8 ;	1—6=8
	36 pieces=90 C.ft.	
	Grand Total ...	56 pieces = 122 C.ft.

K. REVANNA,
District Forest Officer.

KOLAR DIVISION.

Tender Notice dated 30th April 1927.

Notice is hereby given that sealed tenders will be received at the office of the Executive Engineer, Kolar Division, up to 2 P.M., on 21st May 1927 for restoring Mallampalli breached minor Tank Reg. No. 200 of Srinivaspur Taluk. An approximate estimate of quantities is given below. These quantities are not guaranteed. The work should be completed by the end of June 1928.

2. The plans, detailed estimate and conditions may be seen at the Executive Engineer's Office at Kolar, between the hours of 10 A.M. and 5 P.M.

3. Tenders should be submitted on printed forms which may be obtained from the Executive Engineer. The tenders should be accompanied by a statement in the form given below, showing the rates at which the different items specified will be executed :—

Description of work	Unit of work	Rate per unit

4. Each tender must be accompanied by a deposit of Rs. 500 in cash or Government Promissory Notes, as earnest money, and be superscribed "Tender for restoring Mallampalli breached minor Tank" in default of which, tenders will be rejected.

5. The final acceptance of any tender will rest with the Chief Engineer, who does not bind himself to accept the lowest or any tender or to assign any reason whatever for the rejection of any tender.

6. Within eight days of the acceptance of the tender, the successful competitor will be required to execute the usual contract bond ; in default of which, his tender will be considered cancelled, and his earnest money will be forfeited.

7. The name of the successful competitor, whose tender has been accepted, will be posted on the notice board in the Executive Engineer's Office in due course. No enquiries regarding the acceptance or rejection of a tender will receive any reply.

8. On acceptance of one of the tenders, the earnest money on rejected tenders will be returned.

9. Approximate quantities of work to be done are noted below :—

No.	Items	Per	Quantity
	Breach filling.		
1	Clearing silt	Lump sum	Rs.
2	Clearing loose earth seat of bund to receive potters clay ...	C.yds.	810
3	Cutting steps and grips	,,	1799
4	Earthwork cutting loose end of bund at breach and cutting trenches.	,,	3150
5	Earthwork filling in breach including carting and admixture of 1/5 gravel and consolidation.	,,	2022
6	Earthwork breach filling from earth available from loose end of bund from item No. 4.	,,	2100
7	Puddle wall including lead of 1½ mile for clay	,,	965
8	Gravel for admixture with carting	,,	1271
9	Bailing water	Lump sum	Rs.
10	Excavating wells	Do	
	Bund.		
1	Clearing jungle and prickly pear	Grade	22
2	Cutting grips in top of rear bund	Lump sum	Rs.
3	Earthwork to bund including consolidation	C.yds.	690
4	Turfing with carting	Sys.	1449
5	Old stone revetment	C.yds.	392
6	New stone revetment	,,	1017
7	Gravel backing	,,	538
8	Providing grade stones	No.	22
9	Providing date stones	No.	1
10	Providing Regd. No. stones	,,	1
11	Providing gauge stones	,,	1
12	Protective works such as construction of groins, etc. ...	Lump sum	Rs.
13	Carting earth from weir side and using to bund with consolidation.	C.yd.	620
	Sluice.		
1	Repairs to sluice (newly built) and providing plug and rod ...	Lump sum	Rs.
	Waste weir.		
1	Earthwork excavation for foundation ...	C.yd.	311
2	Burnt brick in surki mortar	C.ft.	1420
3	Burnt stone slabs	S.ft.	715
4	Surki plastering	S.qrs.	4·49
5	Rough stone work, new	C.yd.	167
6	Cutting joggels	No.	22
7	Earthwork draft clearing	C.yd.	3105

S. SRINIVASA IYER,
Executive Engineer.